

Collision Center of Orlando
4581 North John Young Parkway, Orlando, Florida



Client: Glenview Auto body, Inc.
Architect: The JRB Group
Role: Construction Manager

International Contractors, Inc. constructed a new 13,140 SF auto body repair facility for Glenview Auto Body, Inc. in Orlando, FL.

As Construction Manager, ICI provided upfront conceptual and detailed budgets using preliminary site, elevation and footprint drawings. Our team worked with the architect and owner at each phase of the project to ensure that designs proceeded in accordance with the established budget.

The facility is equipped with 15 service bays, all outfitted with Italian

heating systems. The structure was built of a tilt-up concrete wall system. The entire wall system was in place by the end of one workday.

A long arch canopy defines the building's facade. The glass wall at the end of the arch, pierced by the support structure, appears to be suspended as a curtain might be.

The 1.6 acres that surround the building is landscaped with indigenous vegetation. Retention ponds were installed in the adjacent areas to protect against flood damage. ICI also constructed a new parking lot.



INTERNATIONAL CONTRACTORS, INC.

977 S. Route 83, Elmhurst, Illinois 60126

Phone: 630-834-8043

Fax: 630-834-8046

www.iciinc.com